**To:** gmurphy@mbakercorp.com[gmurphy@mbakercorp.com];

Prescott.brownell@noaa.gov[Prescott.brownell@noaa.gov]; Laycock, Kelly[Laycock.Kelly@epa.gov];

jaclyn.daly@noaa.gov[jaclyn.daly@noaa.gov]

**Cc:** connollyms@scdot.org[connollyms@scdot.org];

marshats@dhec.sc.gov[marshats@dhec.sc.gov]

From: Mark Caldwell

**Sent:** Fri 2/1/2013 3:09:07 PM

Subject: RE: Joiner Bay Mitigation - Revised Figure 13

Gordon.

As a follow-up to yesterday's call, and to prepare for the February meeting here are some issues that the FWS believes important. These comments address the plan as a whole, not specific to Drain-Mod.

- 1. What is the contingency plan in the event of site failure? We are not only referring to failure to meet success criteria but also in the event the site is not approved or lawsuits delay action.
- 2. As another contingency consideration, has SCDOT considered the long term use of this site (assuming approved) if I-73 is abandoned or shelved? Has SCDOT considered using the site as a bank? For future multiple projects in the service area?
- 3. Perhaps I misheard or misunderstood part of the conversation but is SCDOT seeking a separate permit for this work? If so, any permit application should include the stream component site so that we may provide a comprehensive review.
- 4. I did not hear any discussion regarding the reference site. Would there be any value to calibrating the Drain Mod using the reference site?

Mark A. Caldwell

U.S. Fish and Wildlife Service

South Carolina Ecological Services

176 Croghan Spur Road, Suite 200

Charleston, SC 29407

843-727-4707 ext 215

843-727-4218 - facsimile

From: gmurphy@mbakercorp.com [mailto:gmurphy@mbakercorp.com]

Sent: Wednesday, January 30, 2013 5:35 PM

To: mark\_caldwell@fws.gov; Prescott.brownell@noaa.gov; Laycock.Kelly@epamail.epa.gov;

jaclyn.daly@noaa.gov

Cc: connollyms@scdot.org; marshats@dhec.sc.gov; gmurphy@mbakercorp.com

Subject: Joiner Bay Mitigation - Revised Figure 13



gmurphy@mbakercorp.com has sent you attachments using Baker eFTP

During the December 3rd site visit to Joiner Bay, a request was made to include the boundaries of hydrologically impaired and drained wetlands that are shown on Figure 16, on Figure 13 as well. That has been done and a copy will be distributed at the meeting tomorrow afternoon. We wanted you to have a copy to look at when we discuss the Figure.

Message

Text:

If any additional material will be discussed or handed out at the meeting, we'll email it to you before the meeting.

Gordon

File(s) Uploaded:

Mit\_Plan\_Fig13\_Gauge\_Location\_051612.pdf

To retrieve these attachments, click on the secure link below. https://eftp.mbakercorp.com:443?wtcQID=S1NXVVdCU09GQjpUUHVFRW44Zg==/

Access to this information will expire on 2/6/2013 12:00:00 AM NOTE: Some companies have policies at their sites that prohibit the above link to be accessed by just clicking on the link. If this is the case, just copy and paste the entire URL link (including the equal signs) into your browser. If you need additional assistance, contact the Michael Baker IT Support Desk at 1-866-447-6333 or e-mail us at DigitalServices@mbakercorp.com

## Legal Disclaimer:

This website is intended solely for use by the Michael Baker Corporation, its affiliates, clients, subcontractors, and other designated parties. All information utilized on this website is for designated recipients only. Any dissemination, distribution or copying of this material by any individual other than the said designated recipients is strictly prohibited. The Michael Baker Corporation, its affiliates and employees, makes no representation or warranty (express or implied) as to the merchantability or fitness for a

particular purpose of any documents or information available from this website and therefore assumes neither legal liability nor responsibility for the accuracy, completeness, technical/ scientific quality or usefulness of said documents or information